

**Document ID# 1743460**  
**2005 Cadillac CTS**

---

# **Heated Seat Inoperative After Repair Within One Week of Usage (Replace Heated Seat Control Module) #05-08-50-003A - (Dec 13, 2005)**

Heated Seat Inoperative After Repair Within One Week of Usage (Replace Heated Seat Control Module)

2002-2005 Buick LeSabre

2003-2005 Cadillac CTS

2004-2005 Cadillac SRX

2005 Chevrolet Corvette

2002-2003 Oldsmobile Aurora

2002-2005 Pontiac Bonneville

This bulletin is being revised to add models (2005 Chevrolet Corvette, 2002-2003 Oldsmobile Aurora) and remove the 2005 Cadillac STS. Please discard Corporate Bulletin Number 05-08-50-003 (Section 08 - Body & Accessories).

## **Condition**

Some customers may comment that the heated seat function is inoperative again, one week or less after repair for the same concern was completed. The technician may have previously replaced the seat heater element and heated seat control module assembly, and the new module may be inoperative.

## **Cause**

Electrostatic discharge from the seat may cause the heated seat control module to become inoperative.

**Correction**

Replace the heated seat module with the redesigned heated seat control module assembly, P/N 10399538.

**Parts Information**

<b>Part Number</b>	<b>Description</b>	<b>Qty</b>
10399538	Module Asm-Heater Control	1

**Warranty Information**

For vehicles repaired under warranty, use:

<b>Labor Operation</b>	<b>Description</b>	<b>Labor Time</b>
C7166	Module, Control Heated Seat Front Right - Replace	Use Published Labor Operation Time
C7167	Module, Control Heated Seat Front Left - Replace	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT  
VOLUNTARY  
TECHNICIAN  
CERTIFICATION**

**© Copyright General Motors Corporation. All Rights Reserved.**

**Document ID# 1743460  
2005 Cadillac CTS**