

Document ID# 1553736

2004 Cadillac CTS

03-05 Cadillac CTS SRX STS DTC P0442 - EVAP System Servicing - kw canister emissions fuel leak line mL part pipe SES tank tube vent valve #PIC3181 - (Oct 6, 2004)

03 - 05 Cadillac CTS SRX STS DTC P0442. Evap System Servicing

The following diagnosis might be helpful if the vehicle exhibits the symptom described in the PI.

Condition/Concern:

Diagnosis of an SES light on and DTC P0442 leads to a leak at the convoluted tube (vent valve pipe) from fuel tank to canister.

Recommendation/Instructions:

The fuel tank must be replaced. The tank will come with a new vent valve and tube. The vent valve and tube are not serviced separately from the tank assembly. Do not transfer the tube from the service tank. Note: canister and purge pipe are serviced separately.

Please follow this diagnosis process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed. If these steps do not resolve the condition, please contact GM TAC for further diagnostic assistance.

Models:

(2003-2005 Cadillac CTS) and (2004-2005 Cadillac SRX) and (2005 Cadillac STS)

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT
VOLUNTARY
TECHNICIAN
CERTIFICATION

© Copyright General Motors Corporation. All Rights Reserved.

Document ID# 1553736
2004 Cadillac CTS