

| Oil Filters | GM Part Number | Height | O.D. | Anti-Drain Back | Filtration | Flow | Cost |
|--|----------------|----------------|-------------------|-----------------|---------------|--------|---------|
| AC Delco | PF44 | no longer made | | | | | |
| AC Delco ***Original*** | PF46 | | | | | | \$3.50 |
| AC Delco | PF58 | (long) | | | | | |
| AC Delco | PF59 | (long) | | | | | |
| AC Delco Ultraguard Gold | UPF44 | 25329389 | | | 5 microns | | \$8.50 |
| AC Delco Ultraguard Gold | UPF58 | | | | 5 microns | | |
| Advance Auto | AA3506 | | | | | | \$6.00 |
| Amsoil | ASF30 | (long) | | | | | |
| Baldwin | B31 | | | | | | |
| Balkamp (K&N) | BK7355556 | | | | | | \$12.00 |
| Bosch | ??? | | | | | | |
| Deutsch | 377 | | | | | | |
| Fram Extra Guard | PH3506 | | | | | | \$4.00 |
| Fram Extra Guard | PH3675 | (long) | | | | | |
| Fram Tough Guard | TG3506 | | | | | | \$6.00 |
| Hard Driver | HD08 | (long) | | | | | |
| K&N | HP-1007 | 3.8" | 3" | Y | 10-20 microns | 16 gpm | \$10.00 |
| K&N | HP-2006 | 4.58" | 3" | Y | 10-20 microns | 16 gpm | |
| Mobil1 | M1-107 | | | | | | \$12.00 |
| Mobil1 | M1-206 | (long) | | | | | |
| Motorcraft | FL330 | | | | | | |
| Motorcraft | FL331 | (long) | | | | | |
| NAPA | 1045 | (long) | | | | | |
| NAPA Gold | FIL1042 | 3.404 | 2.921 | | | | \$6.50 |
| NAPA Nascar | NFI91042 | 3.404 | 2.921 | | | | \$4.00 |
| NAPA Silver | SFI21042 | 3.404 | 2.921 | | | | \$3.50 |
| PureOne | PL20123 | (long) | | | | | |
| Purolator | L14006 | | | | | | \$3.50 |
| Purolator | L20123 | (long) | | | | | |
| Purolator | L24007 | | (slightly larger) | | | | |
| Purolator | PL14006 | | | | | | \$6.00 |
| STP | S3506 | | | | | | \$3.00 |
| WIX | 51042 | | | | | | |
| WIX | 54045 | (long) | | | | | |
| Rubber drain plug washer 13/16"-16 Thread | 3536966 | | | | | | \$1.00 |